



Aluminum Sauna Products

An oxygen-protective gray oxide layer forms on the surface of uncoated aluminum. The oxide layer can be removed mechanically with a mild soap suitable for aluminum.

Always try the mildest cleaning method for a small area first. Never mix different types of detergents.

Products should not be cleaned hot or very cold. Do not use special cleaners for aluminum surfaces on other surfaces, and vice versa.

After cleaning, the aluminum surface must always be allowed to dry completely. The exception is cleaning with abrasive polishes, which are removed with a dry cloth.